



LUMAG GmbH • Rudolf-Diesel-Straße 1a • 84375 Kirchdorf/Inn
 Telefon: +49 (0)8571/92556-0 • Fax: +49 (0)8571-92556-19
info@lumag-maschinen.de • www.lumag-maschinen.de

MD-800HPRO/AR

Dumper with hydraulic tipping and roll-off trough

PRODUCT-INFORMATION

Technical Data

MD-800HPRO/AR

Engine	1-cylinder-4-stroke-OHV LONCIN G420F engine for unleaded petrol
Displacement	420 cm ³
Power	9,0 kW
Speed	3.600 rpm
Starting	Recoil starter
Driving system	Gear transmission
Steering system	Steering break
Dump (LxWxH)	1240 x 760 x 400 mm
Ground clearance	130 mm
Max. payload	800 kg
Tipping	Hydraulic and roll-off trough
Hydraulic pump	10 l/min (at 3.600 rpm)
Working pressure	200 bar max.
Gearbox	6 forward gears 2 reverse gears
Dimensions (LxWxH)	2020 x 760 x 1080 mm
Weight (Nt. / Bt.)	430 / 460 kg



Art. No.: MD800HPROAR

EAN: 40 47424 08403 8



Foldable stand-on platform

Accessoire (optional):

- Roll-off trough f. Mini-Dumper MD800HPRO/AR (Art. Nr. 5MD800HPROARM, EAN: 40 47424 08404 5)
- Snow blade f. Mini-Dumper MD800HPRO/AR (Art. Nr. 5MD800HPROSS, EAN: 40 47424 00863 8)

Equipment Features:

Our MD800HPRO/AR is a versatile, gasoline-powered mini crawler dumper with tipping hydraulics, roll-off trough and a stand-on platform for fatigue-free work.

- As a perfect helper for all transport work, the MD-800HPRO/AR provides valuable services in many industries, for a wide range of activities.
- The MD-800HPRO/AR easily transports loads up to 800 kg.
- An extremely slim design and compact dimensions make the MD-800HPRO/AR safely to the job site even through narrow gates and paths.
- Bulk and general cargo is discharged by a hydraulic tipping trough.
- The trough is fitted with rolls and can therefore also be completely parked or picked up again by simply rolling it off.
- The solid steel construction and powerful hydraulic cylinder combined with the simple, intuitive controls make the MD-800HPRO/AR the ideal helper.
- The foldable stand-on platform allows fatigue-free work
- Good grip on slippery, slippery and muddy surfaces due to the crawler undercarriage with rubber tracks.